Payment Voucher

-----

.

. . .

No. : 566 Particulars		Da	ted : 11-Feb-2019 Amount	
Account :			Amount	
Repair & Maintenanc	e Exp		850.00	
	a)			
Through :	ain al A/a			
SBM SB A/c 64004686044 Print On Account of :	cipal A/C			
ch.no: 041743, dt: 11.2.19 & Freeze Tech for changir Bank Transaction Details:	9 , issued in fang tap for wate	avour of Cool er purifier.		
Repair & Maintenance Exp Cheque	11-Feb-2019	850.00		
Amount (in words) :				
INR Eight Hundred Fifty Only			₹ 850.00	*2
				1
( and when a start			Shareda. S	ľ
Receiver's Signature:		Aut	horised Signatory	
Λ			Principal	
Prepared by		M.E. Rajaj	S. Institute of Manage jinagar, BANGALORE	ement E - 10.
9591905214				

BV-274

	REEZE TECHService Report96, Mob. : 98459 51181No. 512rigeration Service DivisionService Report				
Customer Name :	Equipment attended				
Address MES Task A land of O	□ Chiller □ AHU □ FCU □ CT □ Pump □ PKC □ SAC □ CASS				
Address MES Instalue to of Monogrand Rajofnagas 2nd black Contact Person: Banfore					
rayaganagan 2 no black					
Contact Person : Bany one					
Phone (O) :					
Mobile :	called ( opeoing)todero ( odlero				
E-mail :	Model				
Blue Star Office Code :	Asset no.				
Dealer Associate Code :					
Obligation : Contract WTY Paid Service					
Paid Service Mention Receipt No.	Call received by				
Fault/Default Code Description	Date Time				
Tap Broken	Call received on				
	First response on				
	Work completed on				
	Test Measurements (as applicable) Before After Voltage				
Action taken Code Description	Amperes 32 00 000				
	Suction pr. Kg/Cm <sup>2</sup> PSIG     DISCHARGE pr. Kg/Cm <sup>2</sup>				
and the what Top got	Oil pr. Kg/Cm <sup>2</sup> D PSIG D D D D D D D D D D D D D D D D D D D				
DDD Drow and working wormed	Compressor Amps     Image: Compressor Amps       Canvas / Grill temp     Image: Compressor Amps				
	Canvas / Grill temp     ©°F     ©°C       Return Air temp     ©°F     ©°C				
Toll now this new or a new of	Ambient temp				
Follow up action (if any)	Conditioned Space (Room) temp   °F   °C  Chiller Water Inlet  °F  °C  Chiller Water Inlet  Chiller Water Inlet Chiller Water Inlet  Chiller Water Inlet  Chi				
Follow up action (if any)	Chiller Water Outlet   °F  °C				
	Condenser Inlet     □°F     □°C       Condenser Outlet     □°F     □°C				
Customer Comments / Suggestions (if any)					
	Tap Material Used Quantity				
The equipment has been serviced / repaired to my / our satisfaction.					
	and the second s				
NA lessharadas					
Principal Customer's Signature and Company's Seal					
Call attended by BName.					
For any query please email us at : customerservice@bluestarindia.com 24 x 7 Customer Care No. : 1800 209 1177 SMS "SERVICE" To 57575. Visit us at www.bluestarindia.com					
The Experts in Cooling					